Work	Ord	ler ID	513	72
****	171			, , =

Page 1

August 20, 2009 1:31:01 PM

Item ID:

D2013-4

Accept



Setup Start



Revision ID: \mathbf{C}

Item Name:

Mirror Bracket RH, 212

Start Date:

08/20/2009

Start Qty: 5.00

Required Date: 08/24/2009 Req'd Qty: 5.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan: _ WWF

Date: <u>09-08-20</u> Tooling:

Date:

Date:

Date:

Start Stop

Stop



QC:

Sequence ID/

Operation

Revision Nbr

, S.

Description

Set Up/ **Run Hours**

SPC (Y/N):

0.00

0.00

Draw Number Draw Rev.

Plan Accept Qty Code

Reject Qty

Run

Reject Insp. Number Stamp

Draw Nbr

Work Center ID

D2013 Rev C

100

Brake NC

Brake NC

NČ BRAKE

Memo

Memo
1-Punch as per template D2013-T3 and Dwg D2013
2-Flatten ends of D2013-3 tube as per Dwg D2013 using DT8545
3-Bend (1) tube as per Dwg D2013 using Jig DT8201
Identify as D2013-3.

Identify as D2013-3.

QC5- Inspect part completeness to step on W/O

4-Deburr as required

110

Memo

Quality Control

Duit Ac	ospace i	Liu							
W/O:			WO	RK ORDER CHAN	IGES				• •
DATE	STEP	PRO	OCEDURE CHAN	IGE	В	у	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No		PAR #:							
	Res	solution:						Date: _	
NCR:		,	WORK ORDE	R NON-CONFORI	MANCE (N	NCR)		•	
DATE	STEP	Description of NC		***************************************	Section B		Verification	1 Approval	Approval
	SILF	Section A	Initial Chief Eng	Action Descriptio Chief Eng		ign & Date	Section C	Chief Eng	QC Inspector
•					,				
									,
		·							
						*			
•									
	1 1		1 1]		1	1	

Work Order ID 51372



Page 2

August 20, 2009 1:31:01 PM

Item ID:

D2013-4

C

Revision ID: Item Name:

Mirror Bracket RH, 212

Start Date:

08/20/2009

Start Qty: 5.00

Required Date: 08/24/2009



Accept

Setup Start



Stop

Cust Item ID: Req'd Qty: 5.00 **Customer:**

Reference:

Approvals:

Process Plan: _____ Date:

Tooling:

SPC (Y/N):

Set Up/

Run Hours

Date:

Date:

Start Run

Stop



Sequence ID/

Work Center ID

Packaging Packaging

Operation Description

Date:

Identify as per dwg & Stock Location

0.00

0.00

Draw Number

Draw Rev.

Plan Code

Accept Qty

Reject Qty

Reject Number Stamp

Insp.

130

QC

Quality Control

QC21- Final Inspection - Work Order Release

Memo

Memo

0.00

0.00

J 3208.24

W/O:			WC	ORK ORDER CHANG	ES				•	1 3
DATE	STEP	PRO	CEDURE CHA	NGE	Ву	,	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No		PAR #:								
	R	esolution:	Disposition	n:	_ QA: N/0	Clos	ed:		Date: _	
NCR:			WORK ORDI	ER NON-CONFORMA	NCE (N	CR)				
DATE	OTED	Description of NC		Corrective Action Section			Verific	ation	Approvai	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng		gn & ate	Section		Chief Eng	QC Inspector
								1		

August 20, 2009 1:31:01 PM

Work Order ID: 51372

Parent Item:

D2013-4RevC

Parent Item Name: Mirror Bracket RH, 212

Comments:



Start Date: 08/20/2009

Required Date: 08/24/2009

Start Qty: 5.00

Required Qty: 5.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
M304TR0.750W.049		Purchased	No		•	100	f	319.5510				


304 RD Tube .750 x .049W

Warehouse	Loc Qty	Loc Code	
Location			
Main Warehouse			
MAT	319.5510026		
107518	7.27		
108498	0		
109314	8.5		
110113	0.73		
110271	0.03		
111096	9		
111457	11.43		
111619	13.2700026		
112187	269.321		15 09/08/0

	. oopaoo							
W/O:			WO	RK ORDER CHANG	GES			Tr.
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Categ	ory:	NCR: Yes	No DQA:	Date:	
		solution:						
NCR:		1	WORK ORDE	R NON-CONFORM	ANCE (NCI	₹)		
DATE	STED	Description of NC			tion B	Verification	Approval	Approva
DAIL	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign of Date	Section C	Chief Eng	QC Inspector
				•				
···								
								,



	DESIGN JB	DRAWN BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
	CHECKED	APPROVED	DRAWING NO. F	REV. C
j	KE	100	D2013 SHEET 1	OF 3
	DATE		TITLE	SCALE
	99.06.07		MIRROR BRACKET	NTS
	Α	90.10.22	NEW ISSUE	
	В	94.06.15	REDRAWN	
		99.06.07	REDRAWN CHANGE OF DIMENSIONS	



W/O:		(4)	WO	RK ORDER CHANGE	ES			· · · · · · · · · · · · · · · · · · ·	n # **
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					:				
				-			,		
Part No		PAR #:	Fault Categ	ory:	NCR: Ye	s No D	QA:	Date: _	
	R	esolution:	Disposition	l:	QA: N/C	Closed: _		Date: _	
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NC	R)			
DATE	STEP	Description of NC		Corrective Action Section		Ver	ification	Approval	Approval
	JILI	Section A	Initial Chief Eng	Action Description Chief Eng	Sigr Da	K Se	ection C	Chief Eng	QC inspector
								:	
									ļ
							-		
				•					
								į	
i		·							ļ,

W/O:			WO	RK ORDER CHANG	BES		-1		b + (9
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							1		
Part No	:	PAR #:	Fault Cate	gory:	NCR: Ye	s No D	QA:	Date: _	
	R	esolution:	Disposition	n:	QA: N/C	Closed: _		Date: _	
NCR:			WORK ORDE	R NON-CONFORM	ANCE (NO	R)			
DATE	STEP	Description of NC	<u> </u>		tion B	Veri	fication	Approval	Approval
DAIL	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sigr Da	ı&r _{Se}	ction C	Chief Eng	QC Inspector
									-
							·		
								;	
								<u> </u>	
					į				
		1							

W/O:				WORK ORDER (CHANGES				L, , ,
DATE	STEP		PR	OCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:		PAR #:	Fault Category:	NCR: Ye	es No DC)A:	Date: _	
	Res	olution:		Disposition:	QA: N/C	Closed:		Date:	

NCR:		WORK ORDER NON-CONFORMANCE (NCR)							
		Description of NC		Corrective Action Section B	Verification	A			
DATE	STEP	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector
						-	:		
			ļ						
		· '							
				7					
							-		
				;		1		· 3	